ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0400, W0739, W0406, W0733, W0737, W0369, W0402	NA	SFS 407 Yelahanka Satellite Town
Segment No.	**Total Length (m)**	
3/C-W0400/S084407	245.00	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	47.01	77.571719	13.101438	77.571561	13.101060	W0402	W0400
2	28.04	77.572701	13.101862	77.572754	13.101614	W0400	W0406
3	169.95	77.573145	13.101911	77.571757	13.101436	W0747	W0369

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains in SFS 407 in ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	1000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drains in SFS 407 in ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	003-16-000018
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D) E-PMT-3/WO/70/2016-17	19/05/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
19/05/2016	18/05/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SAMBHASHIVAREDDY		0.00
Phone No.	**E-Mail ID**	
9972741359		

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0400, W0739, W0406, W0733,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-೧೦೬

Field Inspection Details

Number of Trees	Any Other Information	Name
12		PRADEEP
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0400, W0739, W0406, W0733,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0400, W0739, W0406, W0733,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	17/12/2016	16/01/2017	COMPLETED
SE	VASU K M	17/12/2016	16/01/2017	COMPLETED
EE	VASU K M	17/12/2016	16/01/2017	COMPLETED
AEE	ASHOK	17/12/2016	16/01/2017	COMPLETED
AE	PRADEEP	17/12/2016	16/01/2017	COMPLETED
AE	PRADEEP	17/12/2016	16/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0400, W0739, W0406, W0733,